GLP JDC-Line Firmware Change Log

Date:	**21 Juli 22**

Main changes from V0.6.7 to V0.6.9	**July 21, 2022**
BUG FIXES	Fixed: Sometimes the heatsink fan showed an error because of wrong internal tolerances
UPDATE PROCESS	**One file has to be uploaded via DMX/RS485:** 1. Upload: JDC-Line_0.6.9_DMX.bin Via D2PROG or D3PROG When importing the bin file to a DProg make sure that you choose the file type „BIN“ before uploading the file to the programmer. **The fixtures can be updated daisy chain via DMX/RS485. Please make sure that no other DMX receivers or consoles are active on the line and fixtures Control Protocol is set to DMX.**
INFO	**Take care that you don´t lose power or connection during the update. So we don't suggest this update on site!!** **Please make sure that your DProg is at least on V42 and your transfer software programmer app on version 612.**

Main changes from V0.6.6 to V0.6.7	March 15, 2022
BUG FIXES	Fixed: Changeing DMX Modes sometimes not apply the correct DMX Mode and channel amount
UPDATE PROCESS	**One file has to be uploaded via DMX/RS485:** 1. Upload: JDC-Line_0.6.7_DMX.bin Via D2PROG or D3PROG When importing the bin file to a DProg make sure that you choose the file type „BIN“ before uploading the file to the programmer. **The fixtures can be updated daisy chain via DMX/RS485. Please make sure that no other DMX receivers or consoles are active on the line and fixtures Control Protocol is set to DMX.**
INFO	**Take care that you don´t lose power or connection during the update. So we don't suggest this update on site!!** **Please make sure that your DProg is at least on V42 and your transfer software programmer app on version 612.** **If your JDCLine fixtures are below version 0.6.6 the bootloader has to be updated as well. Please see and follow upload instructions for version 0.6.6 as below**
Main changes from V0.6.4 to V0.6.6	**February 23, 2022**

BUG FIXES	• Fixed: RDM Identify • Fixed: Press and Hold Up + Down for 3s will show main fixtures settings • Fixed: DHCP / Custom IP interchanged • Fixed: High sACN /Artnet universes cant be stored • Fixed: Network Packet loss • Fixed: Network Disconnecting from time to time … • Fixed: Dimmer Curves
UPDATE PROCESS	**Two files have to be uploaded in sequence via DMX/RS485, one after the other:** 1. Upload: JDC-Line_0.6.6_BOOTDMX.hex After the update of the new Bootloader is finished please wait about 30 seconds before the second step below 2. Upload: JDC-Line_0.6.6_DMX.hex Both via D2PROG or D3PROG When importing the 2 hex files to a DProg make sure that you choose the file type „Intel Standard hex“ before uploading the files to the programmer. **The fixtures can be updated daisy chain via DMX/RS485. Please make sure that no other DMX receivers or consoles are active on the line and fixtures Control Protocol is set to DMX.**
INFO	**The Update is show critical. (e.g dimmer curves and strobe timings) Take care that you don´t lose power or connection during the update. So we don't suggest this update on site!!**

Main changes from V0.5.3 to V0.6.4 September 25, 2021

BUG FIXES	• Fixed Mode 6 in Art-Net
INFO	Update is Show critical

First Release V0.5.3	**March 26, 2021**
INFO	• New DMX Table

Fieldtest V0.3.5	**October 19, 2020**
INFO	